

**TECHNICAL DATA** 

## Fluke 365 Detachable Jaw True RMS AC/DC Clamp Meter





### **Key features**

- 200 A AC and DC current measurement with detachable jaw
- 600 VAC and DC voltage measurement
- Detachable jaw makes accessing wires and viewing the display easier
- Built in flashlight/torch allows for easy illumination and identification of wires
- CAT III 600 V
- Compact design fits in your hand and can be used while wearing protective equipment
- State of the art signal processing allows for use in noisy electrical environments while providing stable readings
- Large, easy to read, backlight display automatically sets the correct measurement range so you do not need to change switch positions while taking a measurement
- Three-year warranty
- Soft carrying case

# Product overview: Fluke 365 Detachable Jaw True RMS AC/DC Clamp Meter

Be ready for anything.

The Fluke 365 is a rugged meter perfect for jobs where access to wires is difficult. The 365's thin, small jaw is detachable



with a flexible lead, which makes gaining access to wires and viewing the display easier than ever.

## Specifications: Fluke 365 Detachable Jaw True RMS AC/DC Clamp Meter

Electrical Specifications			
AC Current			
Range	200.0 A		
Resolution	0.1 A	0.1 A	
Accuracy	2 % ±5 digits (45 – 65 Hz)		
	2.5 % ±5 digits (65 – 400 Hz)		
Crest Factor	2.5 @ 125 A		
	1.55 @ 200 A		
	Add 2 % for C.F. >2		
DC Current			
Range	200.0 A		
Resolution	0.1 A	0.1 A	
Accuracy	2 % ±5 digits		
AC Voltage			
Range	600.0 V		
Resolution	0.1 V	0.1 V	
Accuracy	1.5 % ±5 digits (45 – 400 Hz)		
DC Voltage			
Range	600.0 V		
Resolution	0.1 V		
Accuracy	1 % ±5 digits		
Resistance			
Range	600.0 Ω/6000	Ω	
Resolution	0.1 Ω/1 Ω		
Accuracy	1 % ±5 digits		
Mechanical Specifications			
Size (L x W x H)		225 x 65 x 46 mm	
25 x 65 x 46 mm		275 g (including batteries)	
Jaw Opening		18 mm	
Detachable Jaw Cable Length		900 mm	



Environmental Specifications			
Operating Temperature	-10 °C to +50 °C		
Storage Temp	-40 °C to +60 °C		
Operating Humidity	Non condensing (<10 °C)		
	≤90 % RH (at 10 °C to 30 °C)		
	≤75 % RH (at 30 °C to 40 °C)		
	≤45 % RH (at 40 °C to 50 °C)		
	(Without Condensation)		
Operating Altitude	2000 meters		
Storage Altitude	12,000 meters		
Temperature Coefficients	0.1 x(specified accuracy)/ °C (<18 °C or > 28 °C)		
Safety Compliance	ANSI/ISA S82.02.01:2004		
	CAN/CSA-C22.2 No. 61010-1-04		
	UL 61010-1:2004		
	EN/IEC 61010-1:2001 to 600V CAT III		
	Pollution Degree 2		
Batteries	2 AA, NEDA 15A, IEC LR6		



## **Ordering information**



#### Fluke 365

Fluke 365 Detachable Jaw True RMS AC/DC Clamp Meter

#### Includes:

- Coated instruction card
- Safety information sheet
- Soft carrying case
- TL75 test leads
- Magnetic hanging strap
- Five AA Alkaline batteries



### Fluke. Keeping your world up and running.®

Fluke Corporation

PO Box 9090, Everett, WA 98206 U.S.A.

For more information call: In the U.S.A. (800) 443-5853 In Canada (800) 36-FLUKE From other countries +1 (425) 446-5500 www.fluke.com ©2024 Fluke Corporation. Specifications subject to change without notice. 06/2024

Modification of this document is not permitted without written permission from Fluke Corporation.